

Thank you for purchasing the **Peg Coat Rack**. This page lists all the contents included in the box. Please take the time to identify the hardware as well as the individual components to this product. As you unpack and prepare for assembly, place the contents on a carpeted or padded area to protect them from damage.

### hardware

Missing hardware? Please call **800.606.6387** for replacements.

1 - bolt

### tools required

allen wrench (included)



### components

1 - top upright

1 - middle upright

1 - bottom upright

1 - base

3 - long arms

3 - short arms

### assembly

A. Attach **bottom upright** to **base** with 1 **bolt** as shown, using an **allen wrench**. Do not over tighten the bolt.

B. Attach **middle upright** to threaded bolt of **bottom upright**. Secure by turning middle upright clockwise.


C. Insert **top upright** into **middle upright** as shown. Turn top upright clockwise to secure.

D. Fit 3 **short arms** into **top upright** as shown. Secure by turning each arm clockwise.

E. Fit 3 **long arms** into **top upright** as shown. Secure by turning each arm clockwise.

Assembly is now complete.

**NOTE: Each hook is able to support 13 lbs evenly distributed.**



**NOTE: Do not over tighten the bolt**

1

### cleaning & care

Clean surfaces with a dry or damp soft cloth. Do not use abrasive cleaners.